CAUTION

To avoid internal circuit board damage, configure the cable as shown in figure 6. The figure shows wiring for a nine-pin connector on the computer. If your computer is a 25-pin type, use a 25-pin to nine-pin adapter cable. Both cables are available from your local distributer or Pacific Scientific Instruments.




Figure 6. Serial Cable